



WM3000U-WM1000U

Product Catalogue

Doc.No: 100352718 Version from: 01.01.2023

Device Voltage Transformer Measuring Unit WM3000U Ord.No. 101562300 (19" Slip-in Unit) The Voltage Transformer Measuring Unit WM3000U is a high-precision comparator unit for comparing the secondary signal from transformer under test with a reference signal supplied by a standard voltage transformer. The resulting error value will be displayed as ratio error and phase displacement on the screen. Operation will be performed via integrated 10.1" touch screen or externally via interface. The unit is able to test VTs (acc. IEC61869-1/3 and ANSI/IEEE C57.13), EVTs (acc. IEC61869-7), LPVTs (acc. IEC61869-11) and digital information of non-conventional transformers (acc. IEC61850-9-2). For further information, please see attached data sheet. Voltage Transformer Measuring Unit WM1000U Ord.No. 101575700 (19" Slip-in Unit) The Voltage Transformer Measuring Unit WM1000U is a high-precision comparator unit for comparing the secondary signal from transformer under test with a reference signal supplied by a standard voltage transformer. The resulting error value will be displayed as ratio error and phase displacement on the screen. Operation will be performed via integrated 10.1" touch screen or externally via interface. The unit is able to test VTs (acc. IEC61869-1/3 and ANSI/IEEE C57.13). For further information, please see attached data sheet. Factory Calibration for New Instrument Factory Calibration for NEW WM3000U, 50 Hz Ord.No. 100519750 incl. ZERA calibration report. CALIBRATION 50Hz This article applies only for a purchase of new device ion Calibration Ca without a DAkkS-calibration. ion Calibration Calibr Load points according to ZERA regulations. Summary of used load points

can be downloaded at www.zera.de.

Additional load points are subject to charges.

CALIBRATION BODHZ - Calibration Calibratio	 Factory Calibration for NEW WM3000U, 60 Hz incl. ZERA calibration report. This article applies only for a purchase of new device without a DAkkS-calibration. Load points according to ZERA regulations. Summary of used load points can be downloaded at www.zera.de. Additional load points are subject to charges. 	Ord.No.	100519752
CALIBRATION 500Hz Elbrates Calibrates Calibrates Calibrates Calibrates Calibrates Calibrates Calibrates Calibrates Calibrates Calibrates Calibrates	 Factory Calibration for NEW WM1000U, 50 Hz incl. ZERA calibration report. This article applies only for a purchase of new device without a DAkkS-calibration. Load points according to ZERA regulations. Summary of used load points can be downloaded at www.zera.de. Additional load points are subject to charges. 	Ord.No.	101045202
CALIBRATION 60H2 Latter Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration	 Factory Calibration for NEW WM1000U, 60 Hz incl. ZERA calibration report. This article applies only for a purchase of new device without a DAkkS-calibration. Load points according to ZERA regulations. Summary of used load points can be downloaded at www.zera.de. Additional load points are subject to charges. 	Ord.No.	101045203
CALIBRATION CALIBRATION CALIBRATION Calibratis calibration calibratis calibration calibratis calibration calibratis calibration calibratis calibration calibratis calibration calibratis calibration calibratis calibration	Option: Factory Calibration of voltage range < 20 mV for new device WM3000U, 50 Hz / 60 Hz incl. ZERA calibration report. Load points according to ZERA regulations. Summary of used load points can be downloaded	Ord.No.	101242342

Subject to change without notice.

at <u>www.zera.de</u>.

DAkkS DKD-Cal	ibration for Instrument		
CALIBRATION CALIBRATION CALIBRATION Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration	 DAkkS/DKD Calibration WM3000U,50 Hz for conventional instrument transformer (VTs) and sensors (EVTs) acc. IEC 61869-1, -3, -7 (old: IEC 60044-2, -7) incl. DAkkS/DKD calibration certificate acc. IEC 17025 Load points according to ZERA regulations. Summary of used load points can be downloaded at www.zera.de. Additional load points are subject to charges. 	Ord.No.	100519641
CALIBRATION CALIBRATION CALIBRATION Calibratice Calibratice Calibratic Calibratice Calibratice Calibratic Calibratice Calibratice Calibratic	DAkkS/DKD Calibration WM3000U,60 Hz for conventional instrument transformer (VTs) and sensors (EVTs) acc. IEC 61869-1, -3, -7 (old: IEC 60044-2, -7) incl. DAkkS/DKD calibration certificate acc. IEC 17025 Load points according to ZERA regulations. Summary of used load points can be downloaded at www.zera.de. Additional load points are subject to charges.	Ord.No.	100519643
CALIBRATION CALIBRATION CALIBRATION Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Dataset on Calibration Calibration Calibration Calibration Calibration	DAkkS/DKD Calibration WM1000U, 50 Hz for conventional instrument transformers (VTs) acc. IEC61869-1, -3 (old IEC 60044-2) incl. DAkkS/DKD calibration certificate acc. IEC 17025 Load points according to ZERA regulations. Summary of used load points can be downloaded at www.zera.de. Additional load points are subject to charges.	Ord.No.	101045352
CALIBRATION CALIBRATION CALIBRATION Calibration Calibration Cali- bration Calibration Calibra- tion Calibration Calibra- tion Calibration Calibra- bration Calibration Calibra-	DAkkS/DKD Calibration WM1000U, 60 Hz for conventional instrument transformer (VTs) acc. IEC61869-1, -3 (old: IEC 60044-2) incl. DAkkS/DKD calibration certificate acc. IEC 17025 Load points according to ZERA regulations. Summary of used load points can be downloaded at www.zera.de. Additional load points are subject to charges.	Ord.No.	101045353





Power cord "Plug type H" to IEC 60320 C13", 1.8 m For supply via power socket.

1x Plug type H

• 1x socket IEC 60320 C13

Ord.No. **100929903**

	Power cord "Plug type G (BS 1363) to IEC 60320 C13", 2.5 m For supply via power socket. • 1x Plug type G (BS 1363) • 1x socket IEC 60320 C13	Ord.No.	X00009832
Current and Volt	age Cables (see also Special Accessories)		
	 Laboratory cable with stackable plug, black, 2.0 m Measurement category III (CAT III). 2x stackable 4 mm plugs with rigid insulating sleeve Lead cross section: 2.5 qmm 	Ord.No.	X00006910
	Laboratory cable with stackable plug, yellow/green, 2.0 m Measurement category III (CAT III). • 2x stackable 4 mm plugs with rigid insulating sleeve • Lead cross section: 2.5 qmm	Ord.No.	100804900
Software			
	CheckCon 4 Database based control and visualization software for Transformer Measuring Unit WM3000I/WM1000I and WM3000U/WM1000U incl. transformer type definition tables, testing procedures, automatic evaluation based on predefined error limits, error compensation of reference transformer and recording of measured values.	Ord.No.	100048564
_ ==	Option: DC measurement mode for WM3000U The Measuring Bridges for Voltage Transformers WM3000U will be upgraded to measure DC signals as described in the technical data.	Ord.No.	100078880

´ ===

CALIBRATION CALIBRATION Ballington Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration	Option: Factory Calibration of DC measurement mode for NEW WM3000U incl. ZERA calibration report. Load points according to ZERA regulations. Summary of used load points can be downloaded at www.zera.de. Additional load points are subject to charges.	Ord.No.	101242331
CALIBRATION CALIBRATION Ealibratic calibration calibration calibration calibration calibration the calibration calibration calibration calibration calibration calibration calibration calibration calibration	Option: Factory Re-Calibration of DC measurement mode for WM3000U incl. ZERA calibration report. Load points according to ZERA regulations. Summary of used load points can be downloaded at <u>www.zera.de</u> . Additional load points are subject to charges.	Ord.No.	101242333
Transport (see al	so Special Accessories)		
	 Transport Case 1 with wheels for COM500x; WM3000; WM1000 Ultra High Impact Copolymer Polypropylene case with inlet from rigid foam, designed for 1 Instrument Accessories Overall dimensions: 80,8 cm x 58,7 cm × 48,4 cm (H x W x D) 	Ord.No.	100023908
Standard Access	ories (see also Special Accessories)		
	Mouse Dell MS111 USB connection	Ord.No.	100847000
	Connection Adapter CA500 To connect EVTs/ECTs according IEC61869-7/8 or IEC60044-7/8 via Twin-BNC, BNC and RJ45. With selector switch 1 GOhm/2 MOhm and 10 pF/100 pF.	Ord.No.	101506000

 Dell-Tastatur, (QWERTY) USA/Europe keyboard layout USB connection 	Ord.No.	100846600
 Dell-Tastatur, (QWERTZ) German keyboard layout USB connection 	Ord.No.	100846700
Patch cable RJ45, 1 m	Ord.No.	100161606
Patch cable RJ45, 3 m	Ord.No.	100161607
Patch cable RJ45, 5 m	Ord.No.	100161603



	 Media converter 100Base-TX to 100Base-FX RJ45 to fiber optic cable, multimode 71 x 26 x 94 mm with power supply Note when using with WM3000 / WM1000: You need two converters, two patch cables and one bipolar optical fibre cable for the connection to PC and WM3000 / WM1000. 	Ord.No.	100720801
	Optical fibre cable, 5 m, bipolar • OM2 fibre • Colour: orange	Ord.No.	100720750
	Set - Fuse 1,6 A / time-lag Type 10 pcs.	Ord.No.	101393500
Documentation			
	Complete documentation as pdf files on USB Stick	Ord.No.	100090716
Special Accessor	ies (General)		
	WM1000 / WM3000 Kit	Ord No	100783100



WM1000 / WM3000 Kit Rebuild in desktop unit

Ord.No. 100783100

	Adjustment of WM3000U		
ADJUSTMENT		Ord.No.	10104900
Adjustment	<i>Note:</i> Calibration and Calibration report are not included.		
Adjustment Adjustment Ad- justment Adjustment Adjust- ment Adjustment Adjusment Adjustment Adjustment Ad-			
Acjustment Adjustment Ad- justment Adjustment Adjust-			
	Adjustment of WM1000U		40404000
ADJUSTMENT	Note: Calibration and Calibration report	Ord.No.	10104900
Adjustment Adjustment Adjustment Adjustment Adjustment	are not included.		
justmont Adjustmont Adjust- mont Adjustmont Adjusmont Adjustmont Adjustmont Ad- justmont Adjustmont Adjust-			
ctory Calibra	tion (only for Service)		
	Factory Calibration for WM3000U, 50 Hz		
CALIBRATION	incl. ZERA calibration report.	Ord.No.	10051976
50Hz	Load points according to ZERA regulations.		
Calibration Calibration Cali- bration Calibration Galibra- tion Calibration Calibration Calibration Calibration Cali-	Summary of used load points		
bration Calibration Calibra-	can be downloaded at www.zera.de.		
	Additional load points are subject to charges.		
	Additional load points are subject to charges.		
	Factory Calibration for WM3000U, 60 Hz	Ord.No.	10051976
		Ord.No.	10051976
CALIBRATION 60Hz Calibrates Calibration Calibration	Factory Calibration for WM3000U, 60 Hz incl. ZERA calibration report. Load points according to ZERA regulations.	Ord.No.	10051976
60Hz	Factory Calibration for WM3000U, 60 Hz incl. ZERA calibration report.	Ord.No.	10051976
600Hz Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration	Factory Calibration for WM3000U, 60 Hz incl. ZERA calibration report. Load points according to ZERA regulations. Summary of used load points	Ord.No.	10051976
600Hz Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration	 Factory Calibration for WM3000U, 60 Hz incl. ZERA calibration report. Load points according to ZERA regulations. Summary of used load points can be downloaded at www.zera.de. 	Ord.No.	10051976
600Hz Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration Calibration	 Factory Calibration for WM3000U, 60 Hz incl. ZERA calibration report. Load points according to ZERA regulations. Summary of used load points can be downloaded at www.zera.de. Additional load points are subject to charges. Factory Calibration for WM1000U, 50 Hz 		
600Hz Calibrates Calibrations Calibration Calibrates Calibrations Cali	 Factory Calibration for WM3000U, 60 Hz incl. ZERA calibration report. Load points according to ZERA regulations. Summary of used load points can be downloaded at www.zera.de. Additional load points are subject to charges. 	Ord.No.	10051976
600Hz Literature calibration calibration calibration calibration calibration calibration calibration calibration calibration calibration calibration Calibration 50Hz Lubrature calibration calibration	 Factory Calibration for WM3000U, 60 Hz incl. ZERA calibration report. Load points according to ZERA regulations. Summary of used load points can be downloaded at www.zera.de. Additional load points are subject to charges. Factory Calibration for WM1000U, 50 Hz incl. ZERA calibration report. Load points according to ZERA regulations. 		
600Hz Calibrates Calibrations Calibration Calibrates Calibrations Cali	 Factory Calibration for WM3000U, 60 Hz incl. ZERA calibration report. Load points according to ZERA regulations. Summary of used load points can be downloaded at www.zera.de. Additional load points are subject to charges. Factory Calibration for WM1000U, 50 Hz incl. ZERA calibration report. 		

		\mathbf{P}
CA	LIBR/	TION
6	01	١z
		eration Cali
		on Calibra- Calibration
		eration Cali
bratio	n Calibrati	on Calibra-

Factory Calibration for WM1000U, 60 Hz incl. ZERA calibration report.	Ord.No.	101045253
Load points according to ZERA regulations. Summary of used load points can be downloaded at www.zera.de.		
Additional load points are subject to charges.		



Factory Calibration of voltage range < 20 mV for WM3000U, 50 Hz / 60 Hz incl. ZERA calibration report.

Ord.No. **101242344**

Load points according to ZERA regulations.

Summary of used load points can be downloaded at <u>www.zera.de</u>.



ZERA GmbH Humboldtstrasse 2a D-53639 Koenigswinter Phone: +49 (0)2244 9277-0 E-Mail: zera@zera.de Internet: www.zera.de Managing Director: Horst Wächter Headquarter: Königswinter

Commerzbank Bonn IBAN: DE29 3804 0007 0113 3131 00 SWIFT (BIC): COBADEFF380

Kreissparkasse Köln IBAN: DE15 3705 0299 0001 0784 92 SWIFT (BIC): COKSDE33

HRB 7073 Siegburg VAT-IdNo. DE 218 515 479 WEEE-Reg.Nr. DE 53879641

Notes on using the product catalogue

When ordering, always state the order number.

Pictures can differ from original product.

We follow ZVEI terms of delivery, see on www.zera.de